

TachoAssist

Daily vehicle check · BX24 KZP + trailer C4471 · 20 Oct 2026

⊗ DEFECTS REPORTED · DO NOT DRIVE

OPERATOR

Demo Haulage Ltd

VEHICLE

BX24 KZP · tractor unit · Scania R450 · fleet no. TA021

TRAILER

C4471

DRIVER

James Carter · driver card 1459 7256 3628 0500

CHECK STARTED

20 Oct 2026, 06:19 (UK time)

SENT

20 Oct 2026, 06:31 (UK time)

Defects

4 · Wheels

tyre · trailer axle 2 · left (nearside)

DO NOT DRIVE

Driver's note, as written: "Cut in the tyre sidewall, trailer axle 2, cord showing."




Photo 1 · 20 Oct 2026, 06:31 (UK time)



Photo 2 · 20 Oct 2026, 06:31 (UK time)

3 · Lights and plates

lights

DO NOT DRIVE

Driver's note, as written: "Rear left marker lamp not working."



Photo 1 · 20 Oct 2026, 06:31 (UK time)

Recorded under the DVSA Guide to maintaining roadworthiness (section 3, daily walkaround checks and driver defect reporting) and the DVSA walkaround check guidance. The walkaround check counts as other work on the tachograph. Defect reports are kept for at least 15 months.

Company

REPORTED TO Daniel Brooks · acknowledged 20 Oct 2026, 06:40 (UK time)

REPAIRED 20 Oct 2026 · by Tyre Services Ltd — A. Patel
Trailer tyre replaced, axle 2 left. Marker lamp bulb replaced.

What was checked

DVSA items as numbered on “Carry out daily HGV walkaround checks (gov.uk)”.

Zone	DVSA walkaround items covered	Result
Tachograph	Card in, set to 'other work'; clock, printer paper, no error message	No defect
1 · Cab	3 Dashboard warning lights and gauges; 4 Steering; 5 Horn; 6 Brakes and air build-up; 7 Height marker; 8 Seatbelts; 9 Security and condition of cab, doors and steps	No defect
2 · Visibility	1 Front view (mirrors, cameras, and glass); 2 Windscreen wipers and washers	No defect
3 · Lights and plates	10 Lights and indicators; 24 Number plate; 25 Reflectors; 26 Markings and warning plates	Defect · do not drive
4 · Wheels	18 Spray suppression; 19 Tyres and wheel fixing	Defect · do not drive
5 · Chassis	11 Fuel and oil leaks; 13 Battery security and conditions; 14 Diesel exhaust fluid (AdBlue); 15 Excessive engine exhaust smoke; 16 High voltage emergency cut-off switch; 17 Alternative fuel systems and isolation	No defect
6 · Coupling	20 Brake lines and trailer parking brake; 21 Electrical connections; 22 Coupling security	No defect
7 · Body and load	12 Security of body and wings; 23 Security of load	No defect
Equipment	27 Other equipment	No defect

Driver's declaration

“I confirm I have checked BX24 KZP and trailer C4471 and I report the defects listed.”

JAMES CARTER · confirmed in the Companion app

20 Oct 2026, 06:31 (UK time)